Test Report with XIS-4000 for Butter Box

2020. 03. 10

I. Intellisense Model & Inspection Condition

1	Model	Intellisense XIS-4000	
2	Inspection Condition	X-ray Exposure	90KV , 3.0mA(270W)
		Detector	O.4 mm
		Inspection Speed	40 m/min
3	Test Product	Butter Box 20kg	
4	Test Specimen	SUS, Glass, Ceramic	

Butter Box

Glass

Ceramic

SUS

Steel

III. Test Result

◆ **10 detection criteria for 10 tests**

Impurity Specimen	Inspection Performance			비고
	SUS/Fe	**Ceramic**	**Glass**	
Butter Box	1.0~1.2∅ 99%	4.0∅ 80% 5.0∅ 99%	4.0∅ 80% 5.0∅ 99%	

◆ **Inspection sensitivity is actually dependent upon physical properties of products or test conditions.**

IV. Inspection software image

Smarter Service, *Better Life*